










GARDEN AVENUE



EXPLANATION

- | | | |
|-------------|---|--------------------------------------|
| MW-1 |  | Monitoring Well |
| EA-2 |  | Destroyed Monitoring Well |
| |  | UST Cavity Monitoring Well |
| B-6 |  | Soil Boring |
| C32 |  | Soil sample location |
| |  | Driveway excavation
0.5 ft. depth |
| |  | BART lane excavation |



0 25 50
Scale (ft)

FIGURE

3

Chevron Service Station 9-0206

320 East Millbrae Avenue

Millbrae, California



C A M B R I A

Excavation and Sample Location Map